

## LOCATION & REMOVAL


Installation is made at any position in the M.O.S.T optical ring, usually at the Screen Unit (shown below) or at the CD Changer located in the boot.



## INSTALLATION

### Installation for MOSTAUX-ROV

Insert OPTICAL leads into MOSTAUX-ROV loom and car loom to create loop, see diagram below



INTERFACE

CAR CONNECTOR

To remove the (out) fibre optic cable from the factory connector you will need to remove the black outer casing and push out the blue locking insert. You will need to do the same to insert the cable into the supplied loom. (shown in previous fig)

### Other Connections

Connect the RED cable to 12v+ PERM

Connect the BLACK cable to 12v- GROUND

Connect the BLUE cable to 12v+ to switch audio

Connect the cable AUDIO sockets on the Harness to your audio source

Plug in and mount the interface

## OPERATING INSTRUCTIONS

Your added audio source can now be selected by supplying 12v+ to the blue cable. Possibly using a remote out from the added source, or external switch.

When activated the added audio will switch to override the factory audio. Selecting another source i.e. radio from the head unit, or removing the 12v+ from the blue cable will return to factory audio.

If you have de-activated the added audio source by selecting a factory source you must then, to re-activate the added audio source supply a 12v+ to the Blue cable, this may mean the external switch (if used) will have to be tuned off then on to activate.

It is not recommended to leave the 12v+ supply on the Blue cable when the car is switched off. As it will be active as the car starts and can give the appearance of no audio if the added source is not playing.



## MOSTAUX-ROV

AUDIO INPUT

ALL RANGE ROVER / LANDROVER  
(Touch screen)

ALL (MOST)

NAV TV (Europe) LTD

---



### NAV TV (Europe) LTD

Distribution Centre  
Unit 21B Vale Business Park  
Llandow, Vale of Glamorgan  
CF71 7PF

Telephone: + 44 (0)8445 783 783  
Fax: + 44 (0)1446 77 22 47  
technical@nav.tv

**Disclaimer**

NAV TV (Europe) Ltd is not liable for any incidental, consequential or indirect damages. In case of erratic behavior of the vehicle's electrical system please disconnect the NAV TV product and contact our technical support Team. NAV TV (Europe) Ltd does not assume liability for any diagnostic fees.

---

e11\*72/245\*2004/104\*4020\*00  
RoHS 2002/95/EC—2002/96/EC